Legacy to Enhanced 7800 Replacement Information

Legacy 7800	Enhanced 7800	Comments
RM7890A1015	RM7890A1056	Jumper terminals 6-7 Jumper terminals 3-20 or install Pre-ignition Interlock
	RM7890B1048	Jumper terminals 6-7 Jumper terminals 3-20 or install Pre-ignition Interlock
RM7890A1056	RM7890B1048	B has an output for Shutter Drive
RM7890B1014	RM7890B1048	Jumper terminals 6-7 Jumper terminals 3-20 or install Pre-ignition Interlock
RM7895A1014	RM7897A1002	Jumper terminals 5-20 or install Pre-ignition Interlock
	RM7898A1000	Jumper terminals 5-20 or install Pre-ignition Interlock Jumper terminals 5-19 for Intermittent pilot
RM7895A1048	RM7898A1018	Jumper terminals 5-20 or install Pre-ignition Interlock Jumper terminals 5-19 for Intermittent pilot
RM7895C1012	RM7897A1002	If Delayed Main Valve is NOT used Jumper terminals 5-20 or install Pre-ignition Interlock
	RM7897C1000	Jumper terminals 5-20 or install Pre-ignition Interlock
	RM7898A1000	RM7898 DOES NOT have Delayed Main Valve Jumper terminals 5-20 or install Pre-ignition Interlock
RM7895C1020	RM7898A1018	Jumper terminals 5-20 or install Pre-ignition Interlock RM7898 DOES NOT have Delayed Main Valve

Legacy to Enhanced 7800 Replacement Information

Legacy 7800	Enhanced 7800	Comments
RM7896A1012	RM7897A1002	Jumper terminals 5-20 or install Pre-ignition Interlock Program 15 second Post Purge
	RM7898A1000	Jumper terminals 5-20 or install Pre-ignition Interlock Jumper terminals 5-19 for Intermittent pilot Program 15 second Post Purge
RM7896C1010	RM7897A1002	If Delayed Main Valve is NOT used Jumper terminals 5-20 or install Pre-ignition Interlock Program 15 second Post Purge
	RM7897C1000	Jumper terminals 5-20 for Pre-ignition Interlock Program 15 second Post Purge
	RM7898A1000	RM7898 DOES NOT have Delayed Main Valve Jumper terminals 5-20 or install Pre-ignition Interlock Program 15 second Post Purge
RM7897A1002	RM7898A1000	Jumper terminals 5-19 for Intermittent pilot If Interrupted pilot application-do not jumper 5-19, move pilot from RM7897 terminal 21 and connect to terminal 8 Program 15 second Post Purge if programmed in RM7897
RM7897C1000	RM7898A1000	RM7898 DOES NOT have Delayed Main Valve Jumper terminals 5-19 for Intermittent pilot If Interrupted pilot application-do not jumper 5-19, move pilot from RM7897 terminal 21 and connect to terminal 8 Program 15 second Post Purge if programmed in RM7897

Legacy to Enhanced 7800 Replacement Information

Legacy 7800	Enhanced 7800	Comments
RM7840G1014	RM7840G1022	G1022 DOES NOT have start-up interlock check feature
RM7800G1018	RM7840G1022	Add S7800A1001 display Use S7800A1142 display if VPS is to be used or change Post Purge time G1022 DOES NOT have Dynamic AFS feature (JR3)
RM7840L1018	RM7840L1075	
	RM7800L1087	S7800A1142 display included
RM7800L1012	RM7840L1075	Add S7800A1001 display Use S7800A1142 display if VPS is to be used or change Post Purge time