

Building Control Systems



October 10, 2007

customer.honeywell.com/buildings

TO: Authorized Systems Distributors
 Commercial Controls Distributors
 Authorized Controls Integrators
 Automation and Control Specialists
 Commercial Comfort and Energy Specialists
 Honeywell Building Solutions
 Honeywell Sales Representatives

FROM: Dan Sullivan, Senior Product Manager
 Lina Salah, Product Specialist

SUBJECT: T7350 Handheld Compatibility List Update

BULLETIN: 07- 0159

General Information

Honeywell is pleased to provide a complete list of all the tested and compatible handhelds and smartphones for programming the T7350 thermostats. These handhelds have been tested using the Thermostat Interface Module which is an RS232 cable (OS number 50000083-001) and the Infra Red Thermostat Interface Module (OS number 50014064-001). See the table on the following page for the complete list of tested handhelds and smartphones. We've also included a list of the handhelds and smartphones that we've tested and have found do not work with the T7350.



T7350 with compatible Palm and RS232 cable

T7350 Handheld and Smartphone Compatibility List

The table below shows the compatibility information for handhelds and smartphones that have been tested and work with the T7350. Note that not all models support the use of the RS232 cable.

| Brand | Model | Handheld or smartphone OS | Infra Red Thermostat Interface Module | Thermostat Interface Module (RS232) |
|---------|-------------|---------------------------|---------------------------------------|-------------------------------------|
| Palm | i705 | 4.x | X | X* |
| Palm | m105 | 3.5 | X | X* |
| Palm | Vx | 3.5 | X | X* |
| Palm | m125 | 4.5 | X | X* |
| Palm | Zire 71™ | 5.2.1 | X | X* |
| HandEra | TRGpro | 3.5x | X | X* |
| Palm | m125 | 4.x | | |
| Palm | Tungsten™ C | 5.2.1 | | |
| Palm | Tungsten T | 5.0 | X | X |
| Palm | m125 | 4.x | X | X |
| Palm | Tungsten C | 5.2.1 | X | X |
| Palm | Tungsten T2 | 5.2.1 | X | X |
| Palm | Tungsten T3 | 5.2.1 | X | X |
| Palm | Zire 31 | 5.2.8 | X | |
| Palm | Zire 21 | 5.2.1 | X | |
| Palm | Zire 71 | 5.2.8 | X | |
| Palm | Treo™ 650 | 5.4 | X | |
| Palm | E2 | 5.4 | X | |
| Palm | TX | 5.4 | X | |
| Palm | LifeDrive | 5.4 | X | |
| Sony | PEG-TJ27 | 5.2.1 | X | |
| Treo | 650 | 5.4 | X | |
| Treo | 680 | 5.4.9 | X | |
| Treo | 700p | 5.4.9 | X | |
| Treo | 755p | 5.4.9 | X | |

* RS232 does work but download speeds are considerably slower than the Infra Red Interface Module.

Non-Compatible T7350 Handhelds and Smartphones

The following models have been tested and are not compatible with the T7350:

- Zire 22
- Treo 750
- Treo 700wx
- Treo 700w
- All handhelds and smartphones with Windows Mobile (5.0) operating system